

Statement showing the violation/Encroachment/Action Taken during: 13-9-2018

S.No.	Place	Violation/Encroachments	Name of occupants	Action/Taken	Remarks.
1.	Nundreshi Colony Bemina,	Illegal/un-authorized Construction of 3 <sup>rd</sup> . floor.	Allottee of plot No.34.	During demolition drive the illegal/un-authorized construction portion has been removed at the site mentioned.	Original position Restored.

In addition to that the enforcement team of SDA conduct demolition drive in and around at Bus Stand Parimpura to remove the Radawallaws


